

Page:

1 oF 11

2008

MECHANICAL ENGINEERING - I

SET - D

(a) (b) (c) (d) Inc (a) (c)	Quenching A fully ha Steel is rap When allo duction hard Hardening th	y steels are rapidly ening is the proce ne core	lly drawn at a oil quenched in	J								
(a) (b) (c) (d) Inc (a) (c)	Quenching A fully ha Steel is rap When allo duction hard Hardening th	g steel during trans rdened steel is fina pidly quenched in o y steels are rapidly ening is the proce ne core	lly drawn at a oil quenched in	J								
(b) (c) (d) Inc (a) (c)	A fully hat Steel is rap When allo duction hard	rdened steel is fina pidly quenched in on y steels are rapidly ening is the proce the core	lly drawn at a oil quenched in	J								
(c) (d) Inc (a) (c)	Steel is rap When allo duction hard Hardening th	oidly quenched in only steels are rapidly ening is the processe core	oil quenched in	J								
(a) (c)	Hardening th	ne core	ss of		(c) Steel is rapidly quenched in oil (d) When alloy steels are rapidly quenched in water							
(c)	_			Induction hardening is the process of								
1.1	Selective har	4 1		(b) Uniform hardening								
He		(c) Selective hardening		(d) Hardening surface for wear resistance								
	Heavy water is used in atomic power plants as											
(a)	Fuel	(b) Sour	ce of energy	(c) Lubrio	ant	(d) Moderator						
W	hich one is n	ot the purpose of	heat treatme	nt of steels?								
(b) (c)	Changing the Increasing o	e composition of some percentage of care redecreasing the grandesirable residual	rbon and Si in ain size			•						
A	A cold chisel is made of											
(a)	Mild steel	(b) Cast	iron	(c) H.S.S		(d) High carbon						
\mathbf{A}^{\dagger}	A body which is permanently deformed is said to have undergone											
. ,	Elastic defor Plastic defor		(b) Limit of elastic deformation(d) Uniform deformation									
	The defect responsible for the phenomena of slip, by which most metals deform plastically, is known as											
(a)	Fracture	(b) Twin	nning	(c) Disloc	ation	(d) Strain hardening						
	~	e maximum shearing stre be of diameter equal to										
(a)	(a) $\frac{1}{4}$ × Thickness of plate			(b) $\frac{1}{2}$ × Thickness of plate		ate						
(c)	Plate thickne	ss		(d) 2×plate t	hickness							



Page:

2 of 11

2008

MECHANICAL ENGINEERING - I

SET - D

- 11. On loading a ductile material in excess of a certain value, gradual increase in elongation occurs with time. Such phenomenon is known as
 - (a) Creep
- (b) Fatigue
- (c) Stress concentration (d) None of the above
- 12. The failure occurs at a point in a member, when the maximum shear stress in a bi-axial stress system reaches the shear stress at elastic limit in simple tension test, This is according to
 - (a) Rankine's theory
- (b) Guest's theory
- (c) Lame's theory
- (d) None of the above

- 13. The function of a washer is
 - (a) To fill the axial gap

- (b) To provide cushioning effect
- (c) To absorb shocks and vibrations
- (d) To provide bearing area
- 14. Surface endurance limit of gear material depends on its
 - (a) Surface hardness
- (b) Modulus of elasticity
- (c) Elastic strength
- (d) All of the above

- 15. A double strap butt joint is always in
 - (a) Single shear
- (b) Double shear
- (c) Either single or double shear
- (d) None of the above

16. If $y = \tan^{-1} \frac{2x}{1 - x^2}$, then $\frac{dy}{dx}$ is

(a)
$$\frac{2}{1+x^2}$$

(b)
$$\frac{2}{1-x^2}$$

(c)
$$\frac{1}{1+x^2}$$

(c)
$$\frac{1}{1+x^2}$$
 (d) $\frac{2x}{\sqrt{1+x^2}}$

- 17. Rivets are made of
 - (a) Soft material
- (b) Hard material
- (c) Ductile material
- (d) Brittle material
- 18. The purpose of providing multiple collars on a flat collar pivot bearing is to
 - (a) Increase frictional resistance
 - (b) To establish self sustaining bearing conditions
 - (c) Distribute the frictional load because of limiting friction
 - (d) Distribute the axial load because of limiting bearing pressure on a collar
- 19. Angle of dwell of cam is defined as the angle
 - (a) during which the follower returns to its initial position
 - (b) of rotation of the cam for definite displacement of the follower
 - (c) through which the cam rotates during the period in which the follower remains in the highest position
 - (d) moved by the cam from the instant the follower begins to rise, till it reaches its highest position
- 20. The supply of working fluid to the engine to suit the load conditions is controlled by
 - (a) Meyer's expansion valve (b) D-slide valve (c) Governor
- (d) Throttle valve



Page:

3 of 11

2008

MECHANICAL ENGINEERING - I

SET - D

- 21. A pantograph is a device that reproduces a displacement
 - (a) On the same scale
- (b) On any scale
- (c) On reduced scale
- (d) On enlarged scale
- 22. In the case of gyroscopic effect, the planes of spin, gyroscopic couple and precession are
 - (a) In same plane

- (b) In different planes
- (c) Any two in perpendicular planes and third in different plane
- (d) Mutually perpendicular
- 23. Which of the following is a lower pair?
 - (a) Piston and cylinder
- (b) Cam and follower
- (c) Belt drive
- (d) Gear
- 24. Match List-I (measuring Devices) with List-II (Measuring parameter) and select the correct answ using the codes given below the lists

	List #1
Dev	rice
A	Pitot tube
В	Micro-manometer
C	Pipe bend meter
D	Wall pressure tap

Par	ameter
1	Flow static pressure
2	Rate of flow (indirect)
3	Differential pressure
4	Flow stagnation pressure

- A
 B
 C
 D

 (a)
 1
 3
 2
 4

 (b)
 4
 3
 2
 1

 (c)
 1
 2
 3
 4

 (d)
 4
 2
 3
 1
- 25. The following data pertain to a worker: base rate = Rs. 20 per hour Time taken for completing the job = 2 hours Standard time = 3hours

Under Halsey plan the total earning of the worker is

- (a) Rs. 36.67
- **(b)** Rs.40.67
- (c) Rs.46.67
- (d) Rs.56.57
- 26. What is the correct sequence of the following parameters in order of their maximum to minimum influence on tool life?
 - 1. Feed rate
 - 2. Depth of cut
 - 3. Cutting speed

Select the correct answer using the codes given below

- (a) 1,2,3
- **(b)** 3,2,1
- (c) 2,3,1
- (d) 3,1,2



Page:

4 of 11

2008

MECHANICAL ENGINEERING - I

SET - D

27.	Given that cutting speed = $9 m/\text{min}$, the return time to cutting time ratio is = 1:2 the feed rate =							
	0.3 mm/stroke, the clearance at each of cut = 25 mm and that the plate Is fixed 700 mm side along the direction of tool travel, the time required for finishing one flat surface of a plate of size 700 x 300 mm in a shaper, will be							
	(a) 10 min	(b) 12.5 min	(c) 15 min	(d) 20 min				
28.	The least count of a metric vernier caliper having 25 divisions on vernier scale, matching with 24 divisions of main scale (1 main scale divisions= $0.5~\mathrm{mm}$) is							
	(a) 0.005 mm	(b) 0.01 mm	(c) 0.02 mm	(d) 0.005mm				
29.	Standards to be used for reference purposes in laboratories and workshops are termed as							
	(a) Primary standards	(b) Secondary standards	(c) Tertiary standard	ds (d) Working standards				
30.	For achieving a spec controlled is	r achieving a specific surface finish in single point turning the most important factor to be atrolled is						
	(a) Depth of cut	(b) Cutting speed	(c) Feed	(d) Tool rake angle				
31.	Interchangeability can be achieved by							
	(a) Standardisation	(b) Better process planning	(c) Simplification	(d) Better product planning				
32.	The centre and radius of the circle $z\overline{z} - (2+3i)z - (2-3i)\overline{z} + 9 = 0$ are							
		(b) $(2,-3),2$						
33.	Enlarging an existing circular hole with rotating single point tool is called							
	(a) Boring	(b) Drilling	(c) Reaming	(d) Internal turning				
34.	Plug gauges are used to							
	 (a) Measure the diameter of the workpieces (b) Measure the diameter of the holes in the workpieces (c) Check the diameter of the holes in the workpieces (d) Check the length of holes in the workpieces 							
35.	Basic shaft and basic hole are those whose upper deviations and lower deviations respectively are							
	(a) +ve,-ve	(b) -ve,+ve	(c) Zero,Zero	(d) None of the above				



Page:

5 of 11

2008

MECHANICAL ENGINEERING - I

SET - D

36. The general equation of continuity for three-dimensional flow of a compressible fluid for steady flow is (where u, v, w are components of velocity in x, y and z directions respectively)

(a)
$$\frac{\partial u}{\partial x} + \frac{\partial v}{\partial y} + \frac{\partial w}{\partial z} = 0$$

(b)
$$\frac{\partial u}{\partial x} = \frac{\partial v}{\partial y} = \frac{\partial w}{\partial z} = 0$$

(c)
$$\frac{\partial u}{\partial x} + \frac{\partial v}{\partial y} + \frac{\partial w}{\partial z} = 1$$

(d)
$$\frac{\partial u}{\partial x} + \frac{\partial v}{\partial y} + \frac{\partial w}{\partial z} = u.v.w$$

37. The density of air at 10° C and 1MPa abs, in SI units is


38. In centrifugal pumps, maximum efficiency is obtained when the blades are

(b) Bent forward

(c) Bent backward

(d) radial

39. If the characteristics of a pump are as shown in fig. What is represented by abscissa



(a) Head

(b) RPM

(c) Discharge

(d) Power

40. A rocket exists exhaust gases with $\rho = 0.5 kg/m^3$ out a 50 cm diameter nozzle at a velocity of $1200 \, m/s$ The thrust, is

41. Which of the following pairs of velocity components u and v satisfy the continuity equation for a two dimensional flow of an incompressible fluid?

(a)
$$u = (2x^2 + 3y^3); v = -3xy$$

(b)
$$u = (3x - y); v = (2x + 3y)$$

(c)
$$u = A \sin xy$$
; $v = -A \sin xy$

(d)
$$u = cx; v = -cv$$

- 42. The flow of a fluid in a pipe takes place from
 - (a) Higher level to lower level

- (b) Small end to large end
- (c) Higher pressure to lower pressure
- (d) Higher energy to lower energy
- 43. An aeroplane is flying at an height of 14km where temperature is -45°C. The speed of the plane is corresponding to M=2. Find the speed of the plane if R=287J/kg K and $\gamma = 1.4$.
 - (a) 2179km/h
- (b) 3010 km/h
- (c) 3250km/h
- (d) 3379km/h



Page:

6 of 11

2008

MECHANICAL ENGINEERING - I

SET - D

44. Pipe 1, branches to three pipes as shown in the given figure. The areas and corresponding velocities are as given in the following table

The value of V_2 in cm per second will be



Pipe Velocity Area (cm per second) (sq cm) 50 1. 20 V₂ 30 2. 10 3. 15 4. 20 10

- (a) 15
- **(b)** 20
- (c) 30

- (d) 35
- 45. The pressure difference measured by a mercury oil differential manometer on the two sides of the orifice meter gives a reading of 50 cm of mercury. Determine the differential pressure head in orifice. Take the specific gravity of oil as 0.9.
 - (a) 7.05 m of oil
- (b) 5.05 m of oil
- (c) 4.75 m of oil
- (d) 3.35 m of oil
- 46. The transition Reynolds number for flow over a flat plate is 5×10^5 . What is the distance from the leading edge at which transition will occur for flow of water with a uniform velocity of 1m/s? (For water, the kinematic viscosity, $v=0.858 \times 10^{-6}$ m²/s)
 - (a) 1 m
- **(b)** 0.43 m
- (c) 43 m
- (d) 103 m
- 47. Pipes of lengths l_1, l_2 etc and diameters d_1, d_2 , etc are connected in series. A single pipe of length $l_1 + l_2 + l_3 + \dots$ having same pressure loss as all pipes in series will have diameter equal to

(a)
$$\left(\frac{l_1 + l_2 + l_3 + \dots}{l_1 / d_1^4 + l_2 / d_2^4 + \dots}\right)^{1/4}$$

(b)
$$\left(\frac{l_1 + l_2 + l_3 + \dots}{l_1 / d_1^5 + l_2 / d_2^5 + \dots} \right)^{1/5}$$

(c)
$$\left(\frac{l_1 + l_2 + l_3 + \dots}{l_1 / d_1^3 + l_2 / d_2^3 + \dots}\right)^{1/3}$$

(d)
$$\left(\frac{l_1 + l_2 + l_3 + \dots}{l_1 / d_1^2 + l_2 / d_2^2 + \dots}\right)^{1/2}$$

48. Let x have the density function $f(x) = \begin{cases} \frac{3}{4}(1-x^2) & \text{if } -1 \le x \le 1 \\ 0 & \text{otherwise} \end{cases}$. Then the probability

$$p\left(\frac{-1}{2} \le x \le \frac{1}{2}\right)$$
 is

- (a) 68.75%
- **(b)** 31.36%
- (c) 95%
- (d) 60.7%
- 49·If thermal conductivity of a material varies as $K_0(1+\alpha T)$, temperature at the center of a 10 cm thick wall of material will be
 - (a) Average of the temperature at two ends of the wall
 - (b) More than the average of the temperature at two ends of the wall
 - (c) Less than the average of the temperature at two ends of the wall



Page:

7 OF 11

2008

MECHANICAL ENGINEERING - I

SET - D

- (d) Depends on the range of temperature
- 50. What is the net radiant interchange per square meter for two very large plates at temperatures 800 K and 500 K respectively? (The emissivity of the hot and cold plates are 0.8 and 0.6 respectively. Stefan Boltzmann constant is 5.67*10⁻⁸W/m² K⁴).
- (a) $10.26 \frac{kW}{m^2}$ (b) $1.026 \frac{kW}{m^2}$ (c) $102.6 \frac{kW}{m^2}$
- 51. A 10 kg solid at 100°C with a specific heat of 0.8kJ/kg.°C is immersed in 40 kg of 20°C liquid with a specific heat of 4.0 kJ/kg ⁰C. Estimate the temperature after a long time if the container is insulated?
 - (a) 30° C
- **(b)** 28° C

- (c) 26°C
- (d) 24° C
- 52. A spherical shaped vessel of 1.4 m outer diameter is 90 mm thick. Find the rate of heat leakage, if the temperature difference between the inner and outer surfaces is 220°C. conductivity of the material of the sphere is 0.083 W/m K.
 - (a) 0.2 kW
- **(b)** 0.5 kW
- (c) 1.088 kW
- (d) 1.6 kW

- $\left(\frac{\partial p}{\partial V}\right)_T \left(\frac{\partial v}{\partial T}\right)_T \left(\frac{\partial T}{\partial p}\right)$ is equal to
 - (a) Zero

- **(b)** 1
- (c) -1
- (d) Infinity
- 54. A well insulated vessel containing air is heated to double the pressure and temperature 150% in excess of initial. The amount of air that leaked is
 - (a) 20%
- **(b)** 22.5%
- (c) 25%

- (d) 0%
- 55. An unconstraint thin circular disc has a concentric hole in it. On heating the diameter of the hole will
 - (a) increase
- (b) decrease
- (c) Remain constant
- (d) first increase then decrease
- 56. The specific heat of diatomic gas at constant pressure is given by (R = universal gas constant and M = molecular weight of gas)
 - (a) $\frac{5}{2} \frac{R}{M}$
- (b) $\frac{5}{2}MR$ (c) $\frac{7}{2}\frac{R}{M}$
- (d) $\frac{7}{2}MR$



2008


INDIAN SPACE RESEARCH ORGANISATION

Page:

8 of 11

MECHANICAL ENGINEERING - I


57. The variation of temperature inside a wall is shown by three different curves. In which case thermal conductivity least varies with temperature



- (a) A
- (b) B
- (c) C
- (d) Cannot be ascertained on the basis of information provided
- 58. Kinetic energy of the molecules in terms of absolute temperature (T) is proportional to
 - (a) T
- (b) T⁴

(c) T^2

- (d) \sqrt{T}
- 59. Which type of heat exchanger an automobile radiator is?
 - (a) Parallel flow type
- (b) Counter flow type
- (c) Regenerator type
- (d) Cross flow type
- 60. Given that Nu=Nusselt number, Re = Reynolds number, Pr = Prandtl number, Sh = Sherwood number, Sc = Schmidt number and Gr = Grashoff number. The functional relationship for free convective heat transfer is given as,
 - (a) Nu = f(Gr, Pr)
- **(b)** Sh = f(Sc, Gr)
- (c) Nu = f(Re, Pr)
- (d) Sh = f(Re, Sc)
- 61. The quantity of heat required to change the temperature of 1 gm of ice from -6° C to -5° C is known as
 - (a) Latent heat of freezing
- (b) Freezing heat (c) Heat of vaporization
- (d) Specific heat
- 62. The spectral energy distribution for a body at temperature T is shown in figure. Now if the temperature of the body is increased



- (a) λ_m Will shift towards right
- (b) λ_m will shift towards left
- (c) The total energy emitted by the body will decrease
- (d) λ_m will remain the same but E_m will increase
- 63. When K is the thermal conductivity, τ is the density and C_p is the specific heat of a substance, then thermal diffusivity is given by

 - (a) $\frac{K}{\tau \cdot C_p}$ (b) $\frac{K \cdot C_p}{\tau}$

- (c) $\frac{\tau.C_p}{K}$
- (d) $\frac{K.\tau}{C}$



Page:

9 of 11

2008

MECHANICAL ENGINEERING - I

64. The determinant of the matrix

$$\begin{bmatrix} 7 & 0 & 0 & 0 \\ 9 & 3 & 0 & 0 \\ 4 & -6 & -2 & 0 \\ 0 & 0 & 0 & 1 \end{bmatrix}$$
i

(a) 0

(b) 1

(c) -42

(d) -68

65. A thin copper wire at 300° is suddenly immersed in water at 30°C. It cools down to 150°C in 70 seconds. It is then reheated to the initial temperature of 300°C and suddenly exposed to air at 30°C where it cools down to 150°C in 200 seconds. This difference in cooling time is due to

(a) Larger specific heat of water

(b) Larger heat transfer coefficient in water

(c) Smaller heat transfer coefficient in water

(d) None of the above

66. A heavy block of mass m is slowly placed on a conveyer belt moving with speed v. If coefficient of friction between block and the belt is μ , the block will slide on the belt through distance

(a)
$$\frac{v}{\mu g}$$

(b)
$$\frac{v^2}{\sqrt{\mu g}}$$

(b)
$$\frac{v^2}{\sqrt{\mu g}}$$
 (c) $\left(\frac{v}{\mu g}\right)^2$ (d) $\frac{v^2}{2\mu g}$

(d)
$$\frac{v^2}{2\mu g}$$

67. A car moving with speed u can be stopped in minimum distance x when brakes are applied. If the speed becomes n times, the minimum distance over which the car can be stopped would take the value

(a)
$$\frac{x}{n}$$

(b) nx

(c) $\frac{x}{n^2}$ (d) n^2x

68. Speed of particle executing simple harmonic motion with amplitude a is half of the maximum speed. At that instant, displacement of the particle is


(a)
$$\frac{a}{2}$$

(b) $\frac{\sqrt{3}}{2}a$

(c) $\frac{2a}{\sqrt{3}}$

(d) $3\sqrt{2}a$

69. Two blocks with masses M and m are in contact with each other and are resting on a horizontal frictionless floor. When horizontal force is applied to the heavier, the blocks accelerate to the right. The force between the two blocks are



(a)
$$\frac{(M+m)F}{m}$$

(b) $\frac{MF}{m}$

(c)
$$\frac{mF}{M}$$

(c) $\frac{mF}{M}$ (d) $\frac{mF}{(M+m)}$



Page:

10 of **11**

2008

MECHANICAL ENGINEERING - I

SET - D

- 70. A stone of mass m at the end of a string of length l is whirled in a vertical circle at a constant speed. The tension in the string will be maximum when the stone is
 - (a) At the top of the circle

(b) Half-way down from the top

- (c) Quarter-way down from the top
- (d) At the bottom of the circle
- 71. Ratio of the radii of the planets P₁ and P₂ is k and ratio of the accelerations due to gravity on them is s. Ratio of escape velocities from them will be

(b) \sqrt{ks} (c) $\sqrt{\frac{k}{s}}$

72. Couple M is applied at C on a simply supported beam AB. The maximum shear on AC will be



(b) M


(c) $\frac{2M}{3}$

- (d) $\frac{M}{2}$
- 73. A short column of external diameter D and internal diameter d, is subjected to a load W, with an eccentricity e, causing zero stress at an extreme fiber. Then the value of 'e' must be

(a)
$$\frac{D^2 + d^2}{8\pi D}$$

(b)
$$\frac{D^2 + d^2}{8D}$$
 (c) $\frac{D^2 - d^2}{8D}$ (d) $\frac{D^3 - d^3}{8D^2}$

74. A beam AB is hinge-supported at its ends and is loaded by couple P.c. as shown in the figure. The magnitude of shearing force at a section x of the beam is



(a) 0

(b) P

(c) P/2L

(d) P.c/2L


- 75. There are two bars of equal length and equal volume and same material, one having stepped diameters and other having uniform diameter. If maximum stress produced in both bars is same, then stored energy will be
 - (a) More in stepped diameter shaft

(b) More in uniform diameter shaft

(c) Equal in both

(d) Depend on other factors

76. The given figure shows the shear force diagram for the beam ABCD. Bending moment in the portion BC of the beam



(a) Is a non-zero constant

(b) Is zero

(c) Varies linearly from B to C

(d) Varies parabolically from B to C



Page:

11 of 11

2008

MECHANICAL ENGINEERING - I

SET - D

77. σ_x, σ_y and τ_{xy} are the rectangular stress components at a point. The radius of Mohr's circle is

(a)
$$\sqrt{\sigma_x^2 - \sigma_y^2 + \tau_{xy}^2}$$

(b)
$$\sqrt{\left(\frac{\sigma_x + \sigma_y}{2}\right)^2 + \tau_{xy}^2}$$

(c)
$$\sqrt{\sigma_y^2 - \sigma_x^2 + \tau_{xy}^2}$$

(d)
$$\sqrt{\frac{(\sigma_y - \sigma_x)^2}{2} + \tau^2_{xy}}$$

78. For the case of a slender column of length L'and flexural rigidity EI built in at its base and free at the top, the Eulers critical buckling load is

(a)
$$\frac{4\pi^2 EI}{I^2}$$
 (b) $\frac{2\pi^2 EI}{L^2}$ (c) $\frac{\pi^2 EI}{L^2}$

(b)
$$\frac{2\pi^2 EI}{L^2}$$

(c)
$$\frac{\pi^2 EI}{L^2}$$

(d)
$$\frac{\pi^2 EI}{4L^2}$$

79. When a beam is subjected to a transverse shearing force, the shear stress in the upper fibers will be

- (a) Maximum
- (c) Minimum
- (c) Zero
- (d) Depends on other data

80. Angle made by 2i-3j+4k with the z-axis is

(a)
$$\cos^{-1}\left(\frac{4}{\sqrt{29}}\right)$$
 (b) $\frac{4}{\sqrt{29}}$

(b)
$$\frac{4}{\sqrt{29}}$$

(c)
$$\sin^{-1}\left(\frac{4}{\sqrt{29}}\right)$$
 (d) $\tan^{-1}\left(\frac{4}{\sqrt{29}}\right)$

(d)
$$\tan^{-1}\left(\frac{4}{\sqrt{29}}\right)$$